DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

69.28 File #:

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013730

Address: 333 Burma Road **Date Inspected:** 01-May-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Xu tao / geng wei No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Components

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed. **BAY#14**

SMAW welding of weld joint 4F-071 located on PCMK SEG3004X of segment 12CW welder is identified as 063326.ZPMC QC is identified as Mr.Li ming yang. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2114-FCM-1.

FCAW welding of weld joint 2F-086 located on PCMK SEG3004V of segment 12CW welder is identified as 047864.ZPMC QC is identified as Mr.Li ming yang. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2132.

BAY#19

FCAW welding of weld joint 2G-022 located on PCMK SB007-048 of Lift 7 welder is identified as 062749. ZPMC QC is identified as Mr. Xu tao . The welding variables recorded by QC appeared to Comply with the WPS-B-T-2232-Tc-U4b-F.

FCAW welding of weld joint 2F-012 located on PCMK SB008-048 of Lift 8 welder is identified as 062757. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2132.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

FCAW welding of weld joint 2G-001 located on PCMK USPL1-638 of U ribs splice welder is identified as 062788. ZPMC QC is identified as Mr. Xu tao . The welding variables recorded by QC appeared to Comply with the WPS-B-T-2232-Tc-U4b-F.

FCAW welding of weld joint 1G-0002 located on PCMK USPL1-639 of U ribs welder is identified as 062788. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2231-Tc-U4b-F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer